



TECHNICAL DATA & USAGE SHEET

HIGH CUT COMBAT HELMET FACE MASK

WITH INTEGRATED GOGGLES

Identifiers

Designation: High Cut Combat Helmet Face Mask

Origin: United States

P/N: 69-0595N

Size: One-Size fits all.

Product Approvals

- Compliant to the high velocity impact requirements of ANSI/ISEA Z871-2015

Features

The UTM one-piece Face Mask with integrated goggles was designed and developed to be worn while using the UTM Man Marker Round (MMR) during Force-on-Force training. It was specifically designed to work with High Cut Combat Helmets while allowing use of the rail and Night Vision Goggles (NVG) / Night Optical Device (NOD) mount systems. It allows for proper cheek/stock weld of shoulder fired weapons. The UTM Protective Face Mask offers face, throat and eye protection that is light wearing, breathable, fully flexible and adaptable to all conditions and environments.

- Light weight, allows full range of motion with excellent vision.
- Breathable construction, unrestricted air flow.

Lenses

Special protective lens for maximum field-of-view with best-in-class anti-fog performance. Provides superior protection from ballistic and environmental threats.

- Abrasion and Fog Resistant Coatings.
- Mask now sits off the face for a cooler and more comfortable fit.
- Enables the user to obtain a full stock weld allowing the full use of iron or electronic sights on the weapon.
- Full head protection is achieved when used with a recommended helmet.
- Adequate space for radio equipment, ear and throat microphones.
- Opening in material allows communication microphone to be outside of the mask in front of the mouth guard for comfort.
- Unrestricted hearing.
- Does not alter head and equipment spatial relationships in training unlike fully enclosed training helmets.
- Offers protection to headset communication equipment.



European Patent number: 1228342 additional patents pending. US patent numbers: 6253682, 6371028, 6427600, 6095051, 6378439, 6422149, 6415718, 6564719 UTM, Ultimate Training Munitions, and the "Breech" logo design are trademarks belonging to UTM Ltd.



TECHNICAL DATA & USAGE SHEET

HIGH CUT COMBAT HELMET FACE MASK WITH INTEGRATED GOGGLES

Care, Cleaning and Maintenance

The UTM High Cut Combat Helmet Face Mask with integrated goggles is intended to be issued as an item of Personal Protective Equipment (PPE). The Face Mask must be cleaned and sanitized upon completion of training. Lens MUST BE removed before washing mask, please review the Revision Lens Removal & Installation instructions before washing the UTM Face Mask.

- The Face Mask cannot be properly sanitized by the use of the disinfectant wipes or sprays. The recommended cleaning method to adequately sanitize the Face Mask is through washing with the use of domestic washing detergent.
- Prior to washing, firmly close the mask's velcro panels. Closing the velcro will prolong the life of both the mask and the velcro panels.
- Wash the mask at 40°C/104°F (warm) with domestic washing detergent.
- To prevent possible damage from incorrect heat settings it is recommended the mask is not tumble dried and that it be allowed to air-dry/line-dry.

To extend the life of the lenses, clean and store your eye wear away from direct sunlight and at room temperature when not in use. To clean and disinfect standard lenses only use the Revision Lens Cleaner (NSN 4240-01-527-4068) or a diluted solution of lukewarm water and dish soap; wash, rinse and blot dry with a microfibre cloth.

- Care should be taken not to scratch the lens at all times. Only use minimal force during cleaning.
- Do not use ammonia, alkaline cleaners, disinfectant sprays/wipes, abrasive cleaning compounds or solvents when cleaning the lens.
- Exposure to or contact with chemical vapors or liquids may cause surface cracks or other damage.
- Examine this lens frequently and replace it immediately if there are any signs of damage or cracking.

Usage Guidelines

- Intended only for supervised training conducted in accordance with UTM safety training protocols by law enforcement, military or professional training and security organizations.
- Verify that all PPE is correctly fitted, ensuring there are no exposed areas of the skin.
- UTM assumes no responsibility for injuries, loss or damage resulting from misuse of this or any of its products.

WARNINGS

- Never remove the lens during training or in or near a training area.
- Do Not use bleach, Do Not Dry Clean, Do Not Tumble Dry and Do Not Iron the UTM Face Mask.
- Use of any solvent other than the approved lens cleaner may lower the impact resistance of the lens, deteriorate the anti-fog coating and will void the warranty.



Disclaimer: Information contained in this publication is provided only for your convenience and is subject to change without notice. UTM MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. UTM disclaims all liability arising from this information and its use. Use of UTM's products is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless UTM from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any UTM intellectual property rights.